



232 Branford Rd.
North Branford, CT 06471
Orders: 203.481.9460
Tech: 203.481.9943
Fax: 203.481.9641

Product Information:

15-962 Honda B-Series Oil Pan

Please note that in some applications modification may be required for proper clearance between the rear rail lip of the oil pan and the engine flywheel.

If your application requires this modification trim back the pan rail lip as needed to provided the required clearance.